
NRSC

Timing Outages Task Group - Executive Summary -

March 6, 2002

Executive Summary - Highlights

- Issue Identified
Timing Outage issue was raised at the NRSC quarterly meeting (11/01)



- Charter
Investigate the recent Timing Outages in order to determine:
 - Root cause(s)
 - Identify existing Best Practices that, if implemented, might have prevented the outages
 - Identify new Best Practices
 - Report to the Committee about recommendations to Service Providers, Network Operators and Equipment Vendors

- Task Group Recommendations to the Committee
 - Accept the proposed three new Best Practices
 - Communicate the three new Best Practices and the office inspection recommendations to the industry
 - Refer the applicable existing BP for further review consideration

- Further Action
 - Mission completed as per charter
 - NRSC should continue to monitor timing related outages


Executive Summary - Impact of Timing Outages

9.4% of all Outages were from Timing Outages



33% of all CCS7 Outages were Timing Outages

Executive Summary - Impact of Timing Outages (cont'd)



- BITS Failures cause significant number of office outages
 - Many Timing Outages were not reported as 'Alarmed'
 - CCS7 Alarms are often the 1st indication of a BITS Outage
- BITS Related Outages
 - Lack Diverse Links to Redundant 'Timing Output' Cards
 - Failure to switch to Redundant Timing Output Card
 - BITS 'Clock Input' card failure (e.g., Stratum 2 or 3)
- Procedural and Craft Activity Error
 - BITS Upgrades failures
 - Dual BITS Fuse Outage
- Power Failure causing office Timing Outages
- No BITS Clock in Office

Executive Summary – Recommendations

- **Propose that the NRSC recommend that Service Providers and Network Operators **conduct office inspections** of BITS and intra-office facilities **on a priority basis**.**
- **Propose Three New Best Practices:**
 - Network Operators and Service Providers should insure that engineering, design, and installation processes address how new network elements are integrated into the office synchronization plan
 - Network Operators and Service Providers should develop management and records keeping tools that accurately track the diversity of internal wiring for office synchronization, including timing leads and power
 - Network Operators and Service Providers should conduct periodic verification of the office synchronization plan and the diversity of timing links, power feeds and alarms

Recommendations: Office Inspections & New Procedures

- Upgrade all **BITS clocks** to models capable of **full A/B Power redundancy**
- Verify that **BITS is on fully protected power** (UPS) with generator, and fed separately (A/B)
- If **D4 channel banks** are used for transporting common channel signaling, there are **special timing considerations**:
 - Redundant SS7 links should be timed from redundant timing sources (e.g., from different BITS timing output cards).
 - » Typically, all D4 Shelves (e.g., six) can be 'daisy chained' with same BITS clock lead. As such, the redundant SS7 Links should terminate on Bays or Shelves with different timing sources
- **Periodic tests for BITS switchover** should be executed where applicable
 - Power (A/B)
 - Input (redundant Clock cards)
 - Output (redundant Timing Output cards)
 - Alarms (e.g., power, input, output, fuse)
- A **one-time physical audit of timing redundancy**, with special attention to SS7 link diversity should be conducted
- **Any outages**, which are determined to have the BITS clock as a contributing cause; whether supplier/service provider/other attributable, should be **shared with the BITS clock supplier** to assist that supplier in improving the quality of their product

NRSC

Timing Outages Task Group Report

March 6, 2002

NRSC Task Group – Timing Outages: Agenda

- **Team Membership**
- **Team Charter**
- **BITS Clock (overview)**
- **2000-01 Timing Outages - Analysis**
- **Recommendations**

NRSC Task Group Members - Timing Outages

Rick Canaday/AT&T

Wayne Chiles/Verizon

Jim Lankford/SBC

Archie McCain/BellSouth

Karl Rauscher/Lucent

Jim Runyon/Lucent

Whitey Thayer/FCC

NRSC Task Group – Timing Outages: CHARTER

Investigate the recent Timing Outages in order to determine:


- Root cause(s)
- Identify existing Best Practices that, if implemented, might have prevented the outages
- Identify new Best Practices
- Report to the Committee about recommendations to Service Providers, Network Operators and Equipment Vendors

Building Integrated Timing Source (BITS)

Conceptual Drawing and Functionality

BITS Clock

- **Stratum 1, 2E, 2, 3**
 - Normal Operation: Clock Reference from Network
 - Stand-Alone Operation: Clock maintains precision (e.g., ST2, ST3)
- **Shelf Powering**
 - Full Protect DC Powering (-48VDC) SHOULD BE Required (UPS + Generator)
 - Redundant (A/B) power SHOULD BE required
 - » Note: Duplex Fuse Outage disables BITS clock (equivalent to total power outage)
- **Redundancy**
 - Stratum Clock MUST BE redundant – should ‘fail over’ gracefully and with Alarms
 - Timing Output (TO) cards MUST BE redundant
 - » Redundant Network Element Timing Leads must terminate on separate Timing Output Cards
 - » Special diversity strategies may be required to handle unique timing applications
 - Special Office Configuration issues
 - » D4 bays are often supported with a single timing lead. Any redundant facilities (e.g., SS7 links) should terminate on separate D4 shelves with diverse timing leads.
- **Alarming**
 - » Loss of Network Reference, Power, CP Outage, Switch to Redundant Pack, ...



2000-2001 Timing Outages – Outage List

Timing Outages Evaluated

- 2000: **20 Outages** (of 203 total outage reports)
- 2001: **16 Outages** (of 181 total outage reports)
- **Timing Outage Report Numbers**
 - Equivalent 'FCC Outage' and 'NRSC Summary' Numbers


2000		2001	
FCC #	NRSC #	FCC #	NRSC #
00-005	00-1-05	01-032	01-1-33
00-010	00-1-10	01-034	01-1-32
00-057	00-2-10	01-058	01-2-19
00-071	00-2-24	01-078	01-2-38
00-092	00-2-44	01-084	01-2-44
00-101	00-3-02	01-090	01-2-49
00-103	00-3-04	01-102	01-3-10
00-116	00-3-16	01-128	01-3-34
00-121	00-3-21	01-130	01-3-36
00-132	00-3-32	01-135	01-3-42
00-138	00-3-38	01-140	01-3-45
00-162	00-3-60	01-155	01-3-60
00-163	00-3-61	01-169	01-4-06
00-165	00-4-01	01-173	01-4-11
00-169	00-4-05	01-176	01-4-08
00-177	00-4-13	01-194	01-4-30
00-182	00-4-17		
00-185	00-4-20		
00-209	00-4-43		
00-222	00-4-56		

Combined 2000-2001: Timing Outage Summary

Total	Sub-Total	Outage Category
10		BITS Related
	2	Shelf Clock Card
	2	Failure - Duplex Failure of Primary & Redundant Timing Output Card
	3	Failure - Simplex 'Timing Output' card (with both Timing Links)
	3	Failure - in Switching to Redundant 'Timing Output' card
10		Craft Activity
	5	Fuse Outage - Craft Error
	2	Other - Craft Error
	3	BITS conversion (old-to-new)
3		Power Outage
12		Other Equipment
1		No BITS Clock

Key:
 BITS - Building Integrated Timing Source
 TO - Timing Output Card (e.g., Composite Clock)

Timing Outages - Summary




- **66% of Timing Outages were the result of**
 - BITS related
 - » Intra-Office Redundancy/Diversity (e.g., facilities, cards, faulty fail-over)
 - Procedural Error by Craft
 - Improper BITS Powering (Commercial and Backup)
- **33% of Timing Outages were from other Network Elements**
 - Unclear if some of these were caused by BITS fail-over problems

Timing Outage – Categories

- **Timing Outages impact on CCS7 Outages**
- **Lack of Alarms for Timing Outages**
- **BITS Redundancy Issues**
- **Power Failure causing office Timing Outage failure**
- **Procedural/Craft Error**

**Each of the above will be discussed
in the
following VGs**


CCS7 Outages



- **57 CCS7 Failures in 2000-01**
- **19 CCS7 Failures caused by Timing Outages**


33% of all CCS7 Outages were caused by Timing Outages

- **14% BITS related**
- **19% Other Timing Outages**



Timing Outages - Alarms


Alarms			Alarms	
BITS			Network Element	
No	No (indirect)	Yes	No	Yes
8	11	7	6	5



- **Timing Outages/BITS failures are often not alarmed**
- **CCS7 Alarms are often 1st indication of a Timing Outage**

Caution: Alarm conditions are not always clearly stated in outage report

BITS Related Outages




Total	Sub-Total	Outage Category
10		BITS Related
	2	Shelf Clock Card
	2	Failure - Duplex Failure of Primary & Redundant Timing Output Card
	3	Failure - Simplex 'Timing Output' card (with both Timing Links)
	3	Failure - in Switching to Redundant 'Timing Output' card

BITS Redundancy Issues


- Lack of diverse links to redundant 'Timing Output' cards
 - Both SS7 Timing Links on same Timing Card
- Failure to switch to Redundant Card
 - Timing Output Card
 - Clock Input Cards

Timing Outages caused by Power Outages



- **POWER FAILURES** causing Timing Outage
 - 8% of all Timing Outages
 - No Backup Power
- **BITS shelf MUST BE on 'Full Protect'**
 - UPS and Generator

Timing Outages: Procedural Error



- **BITS Shelf upgrade failure**
 - Removing timing leads (wires)
 - Clock Input Card Upgrade (to Stratum 2)
 - BITS enhancement (adding dual power feeds)
- **Dual BITS shelf fuse outage**
 - Clearing Rack Space -> Power outage (Fuses)
 - Shorting backplane causing Duplex Fuse Outage
 - » Plastic protective shield was removed
- **Faulty Method Of Procedure (MOP)**
 - BITS Shelf Replacement
 - Lack of Training/Supervision
- **Installation of New Equipment (non-BITS) – Indirect Cause**
 - Installation of fuse panel, power supply & cable removal
- **Other craft activity**
 - Disabling BITS backplane pins

Timing Outages – Other Concerns

- **D4 Channel Banks Configurations**
- **BITS Clock Fail-Over Concern**
- **Intra-Office Diversity or Redundancy**

**Each of the above will be discussed
in the
following VGs**

Timing Outages – D4 Channel Bank Concerns

- **D4 – BITS Issues**
 - Many SS7 links are transported through D4 equipment
 - D4 Shelves can only take a single timing link (No Redundant Timing)
 - Multiple D4 Shelves (or Bays) can be fed by a single timing link
 - If SS7 links are transported through D4 shelves that are timed from the same timing source, then the office is subject to being isolated with a simplex BITS failure

- **Five (5) outages explicitly stated D4 impact (14%)**
 - » **00-209**
 - » **01-032**
 - » **01-130**
 - » **01-169**
 - » **01-194**

Intra-Office Diversity/Redundancy Concerns: Summary

Timing Outages are caused by:

- **Terminating SS7 Links on equipment that is timed from the same BITS Timing Output card**
- **Lack of Redundant BITS Timing Output cards**
- **Failure to switch (or 'Fail-Over') to redundant pack**
- **Termination both SS7 Timing Links on same D4 bay**
 - **A D4 Channel Bank supports only simplex timing**
- **Lack of 'Full Protect' Power to BITS shelf**

Applicable Existing Best Practices – NRIC V

NRIC V BP No.		NRIC V BP No.		NRIC V BP No.
5-501		5-583		5-680
5-509		5-588		5-682
5-510		5-589		5-683
5-514		5-590		5-686
5-528		5-594		5-688
5-529		5-597		5-692
5-532		5-600		5-693
5-540		5-602		5-744
5-546		5-604		5-745
5-548		5-605		5-747
5-549		5-612		5-748
5-550		5-613		5-749
5-551		5-615		5-751
5-552		5-618		5-752
5-553		5-636		5-753
5-554		5-637		5-754
5-557		5-651		5-755
5-559		5-668		5-756
5-565		5-678		5-757
5-567		5-679		

- **Best Practices are available via NRIC web site:
<http://www.nric.org>**
- **Recommendation: Refer these existing BP for further review consideration based on Timing Task Force findings**

Timing Outage Summary – Recommendations

Office Inspection Recommendation

Develop Three New Best Practices

See Details on Following Pages

Recommendations: Office Inspections & New Procedures

- Upgrade all **BITS clocks** to models capable of **full A/B Power redundancy**
- Verify that **BITS is on fully protected power** (UPS) with generator, and fed separately (A/B)
- If **D4 channel banks** are used for transporting common channel signaling, there are **special timing considerations:**
 - Redundant SS7 links should be timed from redundant timing sources (e.g., from different BITS timing output cards)
 - » Typically, all D4 Shelves (e.g., six) can be 'daisy chained' with same BITS clock lead. As such, the redundant SS7 Links should terminate on Bays or Shelves with different timing sources
- **Periodic tests for BITS switchover** should be executed where applicable
 - Power (A/B)
 - Input (redundant Clock cards)
 - Output (redundant Timing Output cards)
 - Alarms (e.g., power, input, output, fuse)
- A **one-time physical audit of timing redundancy**, with special attention to SS7 link diversity should be conducted
- **Any outages**, which are determined to have the BITS clock as a contributing cause; whether supplier/service provider/other attributable, should be **shared with the BITS clock supplier** to assist that supplier in improving the quality of their product

Recommendations: New Best Practices

- Network Operators and Service Providers should insure that engineering, design, and installation processes address how new network elements are integrated into the office synchronization plan
- Network Operators and Service Providers should develop management/records keeping tools that accurately track the diversity of internal wiring for office synchronization, including timing leads and power
- Network Operators and Service Providers should conduct periodic verification of the office synchronization plan and the diversity of timing links, power feeds and alarms

BACKUP VGs

2000 Outage Summary – Timing Outages

- 20 Timing Outage Reports (203# Total) – 9.9%
 - 3 BITS related
 - » 1 – Failure of Simplex Timing Output Cards (Both links on same TO)
 - » 2 – Failure to switch to Redundant Timing Output Card

 - 7 BITS – Craft Activity
 - » 4 - BITS Shelf Fuse Outage (craft error)
 - » 1 – Other Craft Error
 - » 2 - BITS conversion (old to new BITS)

 - 2 Power Outage

 - 8 Other Equipment (e.g., DCS, DACS, Switch)
 - » Some of these may have been BITS related (insufficient evidence)

- Outage Impact
 - 11 - SS7 “A” link outage

Note:
225 Initial Reports before
Withdrawals/duplicates

2001 Outage Summary – Timing Outages

- 16 Timing Outage Reports (181# Total) – 8.8%
 - 7 BITS related
 - » 2 – Shelf Clock Card (e.g., Stratum 2)
 - » 2 – Failure of Redundant Timing Output Cards
 - » 2 – Failure of Simplex Timing Output Cards (Both links on same TO)
 - » 1 – Failure to switch to Redundant Timing Output Card
 - 3 BITS – Craft Activity
 - » 1 BITS Shelf Fuse Outage (craft error)
 - » 1 Other Craft Error – Loose Cable
 - » 1 BITS conversion (old to new BITS)
 - 1 Power Outage
 - 1 No BITS clock (e.g., Loss of Network Synchronization)
 - 4 Other Equipment (e.g., DCS, DACS, Switch)
- Outage Impact
 - 8 - SS7 “A” link outage

Note:

**# 200 Initial Reports before
Withdrawals/duplicates**

2000 NRSC – Outage Summary

- **Failure Category for 20 Timing Outages:**
 - » 11 - CCS – Isolation
 - » 3 - DCS – Software
 - » 1 - DCS – Hardware
 - » 4 - Tandem Switch – Hardware, Software, Other
 - » 1 - CO Power – DC Distribution

- **Root Cause for the Timing Outages**
 - » 11 - Procedural – Service Provider, Other Vendor
 - » 2 - Design – Software; Program Data
 - » 1 - Design - Firmware
 - » 3 - Design – Hardware; Insufficient Component/Network Redundancy/Diversity
 - » 2 - Design – Software Ineffective Fault Recovery/Re-Initialization Action
 - » 3 - Hardware Failure (Perf Unit, Other,

- **Focus Area for the Timing Outages:**
 - » 14 - Signal
 - » 8 – DCS, Switch
 - » 4 – Power
 - » 1 – E911

2001 NRSC – Outage Summary

- **Failure Category for 16 Timing Outages:**
 - » 7 CCS – Isolation
 - » 3 CCS – Links
 - » 3 DCS – Hardware
 - » 1 Tandem Switch – Software
 - » 2 Hardware Failure
 - » 1 ? (01-194)

- **Root Cause for the 16 Timing Outages**
 - » 4 Procedural – Service Provider, Other Vendor
 - » 2 Design – Software
 - » 1 Design - Firmware
 - » 7 Design – Hardware; Insufficient Component/Network Redundancy/Diversity
 - » 2 Design – Software Ineffective Fault Recovery/Re-Initialization Action
 - » 2 Hardware Failure

- **Focus Area for the 16 Timing Outages:**
 - » 12 Signal
 - » 4 DCS